



Thermohygrometer



Model DT-70 TH

Thermo-hygrometer hanging with Brass Bezel
Measures Thermometer (celcius) and Hygrometer (RH)
Ranges : -30 °C - 60 °C; 0 - 100% RH
Dimensions. : 65 mm x 25 mm